

Oil Field Environmental Incident Summary

Incident: 20141014140923 **Date/Time of Notice:** 10/14/2014 14:09

Responsible Party: Paul Rankin INC

Well Operator: LANDTECH ENTERPRISES, LLC

Well Name: ELK DISPOSAL-WHALSTROM 10-2

Field Name: ELK

Well File #: 10128

Date Incident: 10/13/2014 **Time Incident:** 12:02

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 102

Sec: 10

Qtr: NW SE

Location Description: just out side of dikes on facility road 4 bbls salt water ,clean up and removed bad gravel and put in waste dirt containment ,haul in new clay and gravel

Submitted By: Tom Ruland

Received By:

Contact Person: Tom Ruland
PO BOX 1560
SIDNEY, MT 59270-1560

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	3	Barrels		
Other						

Description of Other Released Contaminant:
none

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

facility soil we removed bad soil and put in new

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

no load lines or pot out side of dike

Wastes Disposal Location: water in tanks and soil in approved tank

Agencies Involved:

Updates

Date: 10/28/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping leak, remained on location according to the report. NDIC retains oversight.